

## IP Devices 540

### General Description

Vicon has released an updated IP device package. The new release includes an update to the VNSetup discovery tool following a problem when using it with the H.264 16 channel encoder (described on the next page).

### Included Updates

IP devices 540 include the following:

1. Updated version (4.0) for VNSetup software

### Devices Support and Latest Version

The IP devices supported by this package and their latest firmware software are provided below:

IP Device Type	Latest Firmware provided in 539	Changes from former package (538)
SVFT-IP V910 VN-301T	53.0.22.0 bios 1.0.10.86	No change
KTX-4	5.0.30.47	No change
V910-PoE VN-855 VN-856 Surveyor-Mini	50.70.0.0	No change
H.264 4CH encoder	6.6.5.1	No change
H.264 16CH encoder	6.6.62.1	No change
KRX-3	5.6.1.10	No change

Note:

- This update is not relevant for Vicon I-Onyx 9xx cameras from any series.
- VN-755 IP camera is no longer tested after IP cards version 532.

# Vicon Release Notes

---

## Description of the Issue Fixed

When connecting to the **H.264 16CH** encoder with older versions on VNSetup users in some cases (not always) would apply an update to the encoder and VNSetup would hang and not complete the task.

## Who Should Install the New Package?

This package is **not** a mandatory update and is meant for any user having problems when using older VNSetup and the H.264 16CH encoder or directed to apply one by Vicon.

## Obtaining the IP Device 540 Package

This software package can be downloaded from Vicon's website free of charge through the following address:

<http://www.vicon-security.com/support-technical-support-software-downloads.htm>

The package will added to the next release of ViconNet version 6.x CD.

## Known Limitation

The following limitation exists and will be corrected in a future version:

1. On certain networks, VNSetup will **not** always detect and list all the cameras. Cameras that are not automatically listed can still be accessed manually.
2. In some cases, VNSetup will report a failure of the device to reboot after changes have been made. A refresh to VNSetup recovers from that situation

## Licensing

There is no license required to update drivers.